



GAS BARRIER MEMBRANE INSTALLATION

Jointing the membrane



1

Ensure that the area is free from stones and mortar droppings as these could damage the membrane

2

Roll out the first membrane and apply the Double Sided Jointing Tape 50mm in from the edge

3

Position the second membrane overlapping the first by 150mm. Remove the backing paper from the Double Sided jointing tape approximately 1m at a time and unroll the second membrane. Pressure should be applied to ensure a good seal.

4

Tape down the lap edge using a Single Sided Lap Tape, again apply pressure to ensure a good seal. A hand roller is an ideal tool for this.